AGENCY-REPORT #: FIRE/OTHER	MATERIALS INCIDENT RESPONSE REPORT # SDFD # COUNTY # HIRT
DATE 1/1/90 .	TOTAL TIMEO_5 +
TIME: INITIAL DISPATCHS	CENE ARRIVAL RETURN HOTS TIME IN HOTS
LOCATION <u>3302 Pacific Hwy</u> Street	San Diego 92101 City Thom Bros: Pg/Coord. San Diego Fire
JURISDICTION: FIRE DISTRICT	San Diego Fire PHONE #
SCENE MGR	INCIDENT COMMANDER
	tact Person on Scene): County Haz Mat
SEND BILL TO: NAME	
COMPANY General Dynamics/Co	nvair CONTACT PERSON J. Hardacre CONTACT CO
ADDRESS3302 Pacific Highway,	San Diego CONTACT PERSON OF METHODE CO
PROPERTY OWNER	PHONE 542-7712 PHONE
ADDRESS	((IVIL
HAZARDOUS MATERIALS: DESCRIPTION Acid Etch tank No. 140 Nitric Acid (HNO ₃), Hydrochlorid	acid (HCL)
HAZARDOUS MATERIALS: DESCRIPTION Acid Etch tank No. 140 Nitric Acid (HNO ₃), Hydrochloric REMARKS: (Include description and This is an update to Hirt Report Hardacre, Environmental Mgr., Ge acid etch solution spill did not hole in the concrete sump in the lost. Pacific Treatment is now will be hired to perform soil sa contractor will repair the sump	acid (HCL)
HAZARDOUS MATERIALS: DESCRIPTION Acid Etch tank No. 140 Nitric Acid (HNO ₃), Hydrochloric REMARKS: (Include description and This is an update to Hirt Report Hardacre, Environmental Mgr., Ge acid etch solution spill did not hole in the concrete sump in the lost. Pacific Treatment is now will be hired to perform soil sa contractor will repair the sump tank. HE SAIO SODILM DICHEOIL	d action taken) dated 12/31/89. 'phone conversation with Jerry neral Dynamics/Convair. He explained to me that the go into the sewer system. It emptied through a ground. Reports of 7000 to 12000 gallons were pumping out what they can. A private contractor mpling and extent of contamination. A cement
HAZARDOUS MATERIALS: DESCRIPTION Acid Etch tank No. 140 Nitric Acid (HNO ₃), Hydrochloric REMARKS: (Include description and This is an update to Hirt Report Hardacre, Environmental Mgr., Ge acid etch solution spill did not hole in the concrete sump in the lost. Pacific Treatment is now will be hired to perform soil sa contractor will repair the sump tank. HE SAID SODIUM DICHROM. FIEZOS SAID IT WAS DDITIONAL ACTION REQUIRED: Refer to SAM for follow up. Referred to Regional Board - Jim	d action taken) dated 12/31/89. 'phone conversation with Jerry neral Dynamics/Convair. He explained to me that the go into the sewer system. It emptied through a ground. Reports of 7000 to 12000 gallons were pumping out what they can. A private contractor mpling and extent of contamination. A cement and another contractor will reline the acid etch the has not involved in the Spice, while John
HAZARDOUS MATERIALS: DESCRIPTION Acid Etch tank No. 140 Nitric Acid (HNO3), Hydrochloric REMARKS: (Include description and This is an update to Hirt Report Hardacre, Environmental Mgr., Ge acid etch solution spill did not hole in the concrete sump in the lost. Pacific Treatment is now will be hired to perform soil sa contractor will repair the sump tank. HE SAID SODIUM BICHROM. FIEZOS SMOIT WAS	d action taken) dated 12/31/89. 'phone conversation with Jerry neral Dynamics/Convair. He explained to me that the go into the sewer system. It emptied through a ground. Reports of 7000 to 12000 gallons were pumping out what they can. A private contractor mpling and extent of contamination. A cement and another contractor will reline the acid etch AND LAS NOT INVOLVED IN THE SPILL, WHILE JOHN Munch 265-5114 Manifest #
HAZARDOUS MATERIALS: DESCRIPTION Acid Etch tank No. 140 Nitric Acid (HNO3), Hydrochloric REMARKS: (Include description and This is an update to Hirt Report Hardacre, Environmental Mgr., Ge acid etch solution spill did not hole in the concrete sump in the lost. Pacific Treatment is now will be hired to perform soil sa contractor will repair the sump tank. HE SAID SODIUM BICHROM. FIEZOS SAID IT WAS DDITIONAL ACTION REQUIRED: Refer to SAM for follow up. Referred to Regional Board - Jim OPIES SENT TO: OOP RWQCB CITY HAZ MAT RSON_PREPARING REPORT:	d action taken) dated 12/31/89. 'phone conversation with Jerry neral Dynamics/Convair. He explained to me that the go into the sewer system. It emptied through a ground. Reports of 7000 to 12000 gallons were pumping out what they can. A private contractor mpling and extent of contamination. A cement and another contractor will reline the acid etch the LATE LATE LATE LATE LATE LATE LATE LATE
HAZARDOUS MATERIALS: DESCRIPTION Acid Etch tank No. 140 Nitric Acid (HNO3), Hydrochloric REMARKS: (Include description and This is an update to Hirt Report Hardacre, Environmental Mgr., Ge acid etch solution spill did not hole in the concrete sump in the lost. Pacific Treatment is now will be hired to perform soil sa contractor will repair the sump tank. HE SAID SODIUM DICHRON. FIEZOS SAID IT WAS DDITIONAL ACTION REQUIRED: Refer to SAM for follow up. Referred to Regional Board - Jim OPIES. SENT TO: ODP RWQCB CITY HAZ MAT	d action taken) dated 12/31/89. 'phone conversation with Jerry neral Dynamics/Convair. He explained to me that the go into the sewer system. It emptied through a ground. Reports of 7000 to 12000 gallons were pumping out what they can. A private contractor mpling and extent of contamination. A cement and another contractor will reline the acid etch AND LAS NOT INVOLVED IN THE SPILL, WHILE JOHN Munch 265-5114 Manifest #